

Infrared Thermometer Non Contact

Information

Infrared Thermometer

Without contact with the object, you can test the temperature.

IR point can be displayed clearly contacting the object target point.

°C and °F interchangeable functions.

Selection of different materials was measured emissivity.

Dark screen backlight test board functions.

15 seconds automatically turn off the screen.

9V battery * 1 (included)

Technical Data

Temperature range : -30~550°C (-22~1022°F)

Operating temperature : 0~50°C

Resolution : 0.1°C / 0.1°F

Accuracy : $\pm 2.5\%$ OR 3°C

Emissivity : Selectable (0.85 / 0.90 / 0.95)

Distance to spot ratio : 12:1

Auto power off : 15 seconds

Laser pointer : Class 2 Laser < 1 mW

